




序号	报告编号	发布日期	结论	影像资料
136	GX-B1495/20-6-231358~231362	2023/9/15	所检项目合格	
137	GX-B1310/21-6-23127	2023/9/18	符合标准要求	

138	GX-B1310/21-6-23128	2023/9/18	符合标准要求	 <p>2023 08 24</p>
139	GX-B1427/21-6-23071	2023/9/18	符合标准要求	 <p>2023 08 24</p>
140	GX-B1427/21-6-23072	2023/9/18	符合标准要求	 <p>2023 08 24</p>

141	GX-B1359/21-6-23115	2023/9/19	所检项目合格	
142	GX-B1328/20-6-23122	2023/9/19	所检项目合格	
143	GX-B1328/20-6-23123	2023/9/19	所检项目合格	

144	GX-B1328/20-6-23124	2023/9/19	所检项目合格	
145	GX-B1423/20-6-23945	2023/9/20	综合判定合格	
146	GX-B1423/20-6-23946	2023/9/20	综合判定合格	

147	GX-B1423/20-6-23947	2023/9/20	综合判定合格	
148	GX-B1423/20-6-23948	2023/9/20	综合判定合格	
149	GX-B1423/20-6-23949	2023/9/20	综合判定合格	



150	GX-B1517/20-6-23037	2023/9/21	综合判定合格	
151	GX-B1517/20-6-23038	2023/9/21	综合判定合格	
152	GX-B1598/21-6-23037	2023/9/15	实测钢丝绳有效截面积损失百分比最大为4.41%，小于5%为正常。	

153	GX-B1598/21-6-23038	2023/9/15	实测钢丝绳有效截面积损失百分比最大为3.36%，小于5%为正常。	
154	GX-B1598/21-6-23039	2023/9/15	实测钢丝绳有效截面积损失百分比最大为3.28%，小于5%为正常。	
155	GX-B1598/21-6-23040	2023/9/15	实测钢丝绳有效截面积损失百分比最大为3.58%，小于5%为正常。	

156	GX-B1598/21-6-23041	2023/9/15	实测钢丝绳有效截面积损失百分比最大为4.66%，小于5%为正常。	
157	GX-B1598/21-6-23042	2023/9/15	实测钢丝绳有效截面积损失百分比最大为3.69%，小于5%为正常。	
158	GX-B1520/20-6-23099	2023/9/25	综合判定合格	



159	GX-B1423/20-6-23982	2023/9/26	综合判定合格	
160	GX-B1423/20-6-23983	2023/9/26	综合判定合格	
161	GX-B1423/20-6-23984	2023/9/26	综合判定合格	

162	GX-B1423/20-6-23985	2023/9/26	综合判定合格	
163	GX-B1423/20-6-23986	2023/9/26	综合判定合格	
164	GX-B1423/20-6-23987	2023/9/26	综合判定合格	

165	GX-B1423/20-6-23988	2023/9/26	综合判定合格	
166	GX-B1423/20-6-23989	2023/9/26	综合判定合格	
167	GX-B1423/20-6-23990	2023/9/26	综合判定合格	

168	GX-B1303/21-6-23013	2023/9/27	综合判定合格	
169	GX-B1380/20-6-23026	2023/9/27	所检项目合格	
170	GX-B1301/21-6-23004	2023/9/27	综合判定合格	

171	GX-B1301/21-6-23003	2023/9/27	综合判定合格	
172	GX-B1515/22-6-23012	2023/9/27	所检项目合格	
173	GX-B1515/22-6-23013	2023/9/27	所检项目合格	



174	GX-B1515/22-6-23012	2023/9/27	所检项目合格	
175	GX-B1495/20-6-231363~231373	2023/9/19	所检项目合格	
176	GX-B1310/21-6-23138	2023/9/27	符合标准要求	

177	GX-B1310/21-6-23139	2023/9/27	符合标准要求		 A photograph showing a person in a blue protective suit and mask working on a large, dark, curved industrial component. The person is positioned on the left side of the frame, facing right. The background is dark, and there is a small light source illuminating the scene. In the bottom right corner of the image, the text "2023 09 16" is visible.	
-----	---------------------	-----------	--------	--	--	--