

序号	报告编号	发布日期	结论	影像资料
1	GX-B1548/20-2-23134	2023/12/1	所检项目合格。	
2	GX-B1548/20-2-23135	2023/12/1	所检项目合格。	

3	GX-B1548/20-2-23136	2023/12/1	所检项目合格。	
4	GX-B1309/21-2-23022	2023. 12. 1	所检项目合格。	

5	GX-B1500/21-2-23122	2023. 12. 1	综合判定：合格。	 A photograph showing a worker in a red and blue uniform and a red hard hat standing in a large industrial facility. The floor is wet and reflective. There are various pipes and machinery in the background. A date stamp '2023/11/16' is visible in the bottom right corner of the photo.
6	GX-B1500/21-2-23123	2023. 12. 1	综合判定：合格。	 A photograph showing a worker in a red and blue uniform and a red hard hat standing in a large industrial facility. The floor is wet and reflective. There are various pipes and machinery in the background. A date stamp '2023/11/16' is visible in the bottom right corner of the photo.

7	GX-B1500/21-2-23124	2023. 12. 1	综合判定：合格。	
8	GX-B1500/21-2-23125	2023. 12. 1	综合判定：合格。	

9	GX-B1309/21-2-23023	2023. 12. 1	所检项目合格。	 <p>A photograph showing a worker in a red safety vest and hard hat inspecting a large industrial pipe in a tunnel. The worker is standing on a concrete floor, and the pipe is supported by a metal structure. The background shows other pipes and equipment in the tunnel.</p>
10	GX-B1500/21-2-23126	2023. 12. 1	综合判定：合格。	 <p>A photograph showing a worker in a red safety vest and hard hat inspecting a large industrial pipe in a tunnel. The worker is standing on a concrete floor, and the pipe is supported by a metal structure. The background shows other pipes and equipment in the tunnel.</p>

11	GX-B1500/21-2-23127	2023. 12. 1	综合判定：合格。	
12	GX-B1500/21-2-23128	2023. 12. 1	综合判定：合格。	

13	GX-B1328/20-2-23174	2023. 12. 1	所检项目合格			
14	GX-B1328/20-2-23175	2023. 12. 1	所检项目合格			



15	GX-B1304/21-2-23016	2023. 12. 4	综合判定：合格。		 A photograph showing three workers in grey jackets and red hard hats standing in a factory. They are positioned near a green machine with a blue safety railing. The floor is green with yellow safety lines. A date stamp '2023-11-22' is visible in the bottom right corner of the image.	
16	GX-B1304/21-2-23017	2023. 12. 4	综合判定：合格。		 A photograph showing three workers in grey jackets and red hard hats standing in a factory. They are positioned near a green machine with a blue safety railing. The floor is green with yellow safety lines. A date stamp '2023/11/22' is visible in the bottom right corner of the image.	



17	GX-B1304/21-2-23018	2023. 12. 4	综合判定：合格。		 <p>2023-11-23</p>	
18	GX-B1304/21-2-23019	2023. 12. 4	综合判定：合格。			

19	GX-B1598/21-2-23179	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.84%，小于5%为正常。		
20	GX-B1598/21-2-23180	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.72%，小于5%为正常。		

21	GX-B1598/21-2-23181	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 2.02%，小于5%为正常。	
22	GX-B1598/21-2-23182	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.89%，小于5%为正常。	

23	GX-B1598/21-2-23183	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.83%，小于5%为正常。		
24	GX-B1598/21-2-23184	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.68%，小于5%为正常。		

25	GX-B1598/21-2-23185	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.52%，小于5%为正常。		
26	GX-B1598/21-2-23186	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.79%，小于5%为正常。		

27	GX-B1536/20-2-23004	2023. 12. 4	综合判定：合格。			
28	GX-B1304/21-2-23014	2023/12/4	综合判定：合格。			

29	GX-B1303/21-2-23005	2023/12/4	综合判定：合格。		
30	GX-B1382/21-2-23005	2023/12/4	综合判定：合格。		

31	GX-B1352/21-2-23188~23189	2023/12/4	本次共检矿用防爆低压交流真空馈电开关2台,2台所检项目合格。		
32	GX-B1300/23-2-23014	2023/12/4	综合判定：合格。		



33	GX-B1300/23-2-23015	2023/12/4	综合判定：合格。			
34	GX-B1300/23-2-23016	2023/12/4	综合判定：合格。			

35	GX-B1309/21-2-23022	2023. 12. 1	所检项目合格。	 <p>2023/12/01</p>
36	GX-B1500/21-2-23122	2023. 12. 1	综合判定：合格。	 <p>2023/11/16</p>

37	GX-B1500/21-2-23123	2023. 12. 1	综合判定：合格。	
38	GX-B1500/21-2-23124	2023. 12. 1	综合判定：合格。	

39	GX-B1500/21-2-23125	2023. 12. 1	综合判定：合格。	
40	GX-B1309/21-2-23023	2023. 12. 1	所检项目合格。	

41	GX-B1500/21-2-23126	2023. 12. 1	综合判定：合格。	 A photograph showing a worker in a red hard hat and high-visibility vest inspecting green industrial machinery in a tunnel. The worker is standing on a wooden platform, and the machinery is mounted on a concrete base. The background shows the interior of a tunnel with various pipes and structures. A timestamp '2023/11/10' is visible in the bottom right corner of the image.
42	GX-B1500/21-2-23127	2023. 12. 1	综合判定：合格。	 A photograph showing a worker in a red hard hat and high-visibility vest inspecting green industrial machinery in a tunnel. The worker is standing on a wooden platform, and the machinery is mounted on a concrete base. The background shows the interior of a tunnel with various pipes and structures. A timestamp '2023/11/10' is visible in the bottom right corner of the image.

43	GX-B1500/21-2-23128	2023. 12. 1	综合判定：合格。	
44	GX-B1304/21-2-23014	2023/12/4	综合判定：合格。	

45	GX-B1303/21-2-23005	2023/12/4	综合判定：合格。		
46	GX-B1382/21-2-23005	2023/12/4	综合判定：合格。		

47	GX-B1352/21-2-23188~23189	2023/12/4	本次共检矿用防爆低压交流真空馈电开关2台,2台所检项目合格。		
48	GX-B1300/23-2-23014	2023/12/4	综合判定：合格。		



49	GX-B1300/23-2-23015	2023/12/4	综合判定：合格。		 <p>2023/11/14</p>
50	GX-B1300/23-2-23016	2023/12/4	综合判定：合格。		 <p>2023/11/14</p>

51	GX-B1304/21-2-23016	2023. 12. 4	综合判定：合格。		 A photograph showing three workers in grey jackets and red hard hats standing in a factory. They are positioned near a green machine with a blue safety railing. The floor is green with yellow safety lines. A date stamp '2023-11-22' is visible in the bottom right corner of the image.	
52	GX-B1304/21-2-23017	2023. 12. 4	综合判定：合格。		 A photograph showing three workers in grey jackets and red hard hats standing in a factory. They are positioned near a green machine with a blue safety railing. The floor is green with yellow safety lines. A date stamp '2023/11/22' is visible in the bottom right corner of the image.	

53	GX-B1304/21-2-23018	2023. 12. 4	综合判定：合格。		 A photograph showing three workers in grey safety suits and red hard hats standing in an industrial setting. They are positioned near a large piece of machinery with a yellow and red section. A date stamp '2023-11-23' is visible in the bottom right corner of the image.	
54	GX-B1304/21-2-23019	2023. 12. 4	综合判定：合格。		 A photograph showing three workers in grey safety suits and red hard hats standing in a large industrial hall. They are positioned near a large piece of machinery with a green and yellow section. The floor is blue with yellow safety lines. The date stamp '2023-11-23' is visible in the bottom right corner of the image.	

55	GX-B1598/21-2-23179	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.84%，小于5%为正常。		
56	GX-B1598/21-2-23180	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.72%，小于5%为正常。		

57	GX-B1598/21-2-23181	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 2.02%，小于5%为正常。	
58	GX-B1598/21-2-23182	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.89%，小于5%为正常。	

59	GX-B1598/21-2-23183	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.83%，小于5%为正常。	
60	GX-B1598/21-2-23184	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.68%，小于5%为正常。	

61	GX-B1598/21-2-23185	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.52%，小于5%为正常。	
62	GX-B1598/21-2-23186	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.79%，小于5%为正常。	

63	GX-B1536/20-2-23004	2023.12.4	综合判定：合格。			
64	GX-B1548/20-2-23134	2023/12/1	所检项目合格。			



65	GX-B1548/20-2-23135	2023/12/1	所检项目合格。			
66	GX-B1548/20-2-23136	2023/12/1	所检项目合格。			

67	GX-B1500/21-2-23131	2023. 12. 1	综合判定：合格。			
68	GX-B1500/21-2-23132	2023. 12. 1	综合判定：合格。			

69	GX-B1500/21-2-23133	2023. 12. 1	综合判定：合格。		 <p>A photograph showing an underground tunnel or mine. In the foreground, there is a large piece of industrial machinery, possibly a conveyor or a pump, with various pipes and components. A worker in a red hard hat and light-colored jacket is standing near the machinery. The tunnel walls are rough and rocky. A date stamp '2023/11/22' is visible in the bottom right corner of the image.</p>	
70	GX-B1309/21-2-23024	2023. 12. 1	所检项目合格。		 <p>A photograph of a worker wearing a red hard hat and a light-colored jacket, standing in an underground tunnel. The worker is looking down at something in their hands. The tunnel floor is covered with gravel and debris. There are wooden supports or scaffolding visible on the right side. A date stamp '2023/11/22' is visible in the bottom right corner of the image.</p>	

71	GX-B1598/21-2-23179	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.84%，小于5%为正常。	
72	GX-B1598/21-2-23180	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.72%，小于5%为正常。	

73	GX-B1598/21-2-23181	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 2.02%，小于5%为正常。	
74	GX-B1598/21-2-23182	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.89%，小于5%为正常。	

75	GX-B1598/21-2-23183	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.83%，小于5%为正常。		 <p>2023/11/25</p>
76	GX-B1598/21-2-23184	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.68%，小于5%为正常。		 <p>2023/11/25</p>

77	GX-B1598/21-2-23185	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.52%，小于5%为正常		
78	GX-B1598/21-2-23186	2023. 12. 4	实测钢丝绳有效截面积 损失百分比最大为 1.79%，小于5%为正常。		

79	GX-B1307/20-2-23086	2023. 12. 4	综合判定：合格		 <p>2023/11/24</p>	
80	GX-B1307/20-2-23087	2023. 12. 4	综合判定：合格		 <p>2023/11/24</p>	





81	GX-B1307/20-2-23088	2023. 12. 4	综合判定：合格。		
82	GX-B1307/20-2-23089	2023. 12. 4	综合判定：合格。		

83	GX-B1307/20-2-23090	2023. 12. 4	综合判定：合格。	
84	GX-B1307/20-2-23091	2023. 12. 4	综合判定：合格。	



85	GX-B1307/20-2-23092	2023/12/4	综合判定：合格。	
86	GX-B1307/20-2-23093	2023/12/4	综合判定：合格。	

87	GX-B1598/21-2-23171	2023. 12. 3	实测钢丝绳有效截面积 损失百分比最大为 0.93%，小于5%为正常。	
88	GX-B1598/21-2-23172	2023. 12. 3	实测钢丝绳有效截面积 损失百分比最大为 1.02%，小于5%为正常。	

89	GX-B1310/21-2- 23387	2023. 12. 4	符合标准要求。		 <p>2023/11/25</p>	
90	GX-B1310/21-2- 23388	2023. 12. 4	符合标准要求。		 <p>2023/11/25</p>	

91	GX-B1309/21-2-23025	2023. 12. 4	所检项目合格。			
92	GX-B1309/21-2-23026	2023. 12. 4	所检项目合格。			

93	GX-B1500/21-2-23134	2023. 12. 4	综合判定：合格。		 <p>2023/11/26</p>	
94	GX-B1500/21-2-23135	2023. 12. 4	综合判定：合格。		 <p>2023/11/26</p>	

95	GX-B1500/21-2-23136	2023. 12. 4	综合判定：合格。		
96	GX-B1500/21-2-23137	2023. 12. 4	综合判定：合格。		



97	GX-B1500/21-3-23138	2023. 12. 4	所检项目合格。			
98	GX-B1500/21-3-23139	2023. 12. 4	所检项目合格。			

99	GX-B1500/21-3-23140	2023. 12. 4	所检项目合格。	
100	GX-B1500/21-3-23141	2023. 12. 4	所检项目合格。	

101	GX-B1328/20-2-23176	2023. 12. 4	本次共检绝缘手套 32双，32双所检项目合格。	
102	GX-B1328/20-2-23177	2023. 12. 4	本次共检绝缘鞋32双， 32双所检项目合格。	

103	GX-B1328/20-2-23178	2023. 12. 4	本次共检便携式接地和接地短路装置32组，32组所检项目合格。	
104	GX-B1328/20-2-23179	2023. 12. 4	本次共检验电器32支，32支所检项目合格。	