












序号	报告编号	发布日期	结论	影像资料
9	GX-B1328/20-5-23183	2023.12.8	本次共检绝缘手套20只，20只绝缘手套合格。	
10	GX-B1328/20-5-23184	2023.12.8	本次共检绝缘鞋20只，20只绝缘鞋合格。	
11	GX-B1416/22-5-23029	2023/12/5	综合判定:合格。	

12	GX-B1424/20-5-23050	2023/12/12	依据NB/T 10176-2019单轨吊 车综合判定合格。	
13	GX-B1310/21-5-23299	2023/12/12	符合标准要求。	
14	GX-B1598/21-5-23065	2023. 12. 11	实测钢丝绳有效截面积损失百 分比最大为3.14%，小于 5%为正常。	
15	GX-B1598/21-5-23066	2023. 12. 11	实测钢丝绳有效截面积损失百 分比最大为3.12%，小于 5%为正常。	

16	GX-B1598/21-5-23067	2023. 12. 11	实测钢丝绳有效截面积损失百分比最大为3.14%，小于5%为正常。		
17	GX-B1598/21-5-23068	2023. 12. 11	实测钢丝绳有效截面积损失百分比最大为3.12%，小于5%为正常。		
18	GX-B1598/21-5-23069	2023. 12. 11	实测钢丝绳有效截面积损失百分比最大为3.14%，小于5%为正常。		
19	GX-B1598/21-5-23070	2023. 12. 11	实测钢丝绳有效截面积损失百分比最大为3.12%，小于5%为正常。		

20	GX-B1304/21-5-23007	2023. 12. 11	综合判定：合格。	
21	GX-B1382/21-5-23002	2023. 12. 11	合格。	
22	GX-B1380/20-5-23008	2023. 12. 11	所检项目合格	
23	GX-B1380/20-5-23009	2023. 12. 11	所检项目合格	

24	GX-B1384/16-5-23009	2023.12.11	综合判定：合格。			
----	---------------------	------------	----------	--	---	--