





序号	报告编号	发布日期	结论	影像资料
26	GX-B1321/20-1-23571~23581	2023. 6. 2	本次共检电力电缆11条，11条电力电缆所检项目合格。	
27	GX-B1451/20-1-23336~23343	2023. 6. 7	本次共检高压开关设备8台，8台高压开关设备所检项目合格	
28	GX-B1451/20-1-23344~23356	2023. 6. 7	本次共检高压开关设备13台，13台高压开关设备所检项目合格	

29	GX-B1329/21-1-23037~23046	2023. 6. 7	本次共检氧化锌避雷器10组，10组所检项目合格	 2023/6/7
30	GX-B1329/21-1-23047~23062	2023. 6. 7	本次共检氧化锌避雷器16组，16组所检项目合格	 2023/6/8
31	GX-B1309/21-1-23018	2023. 6. 7	所检项目合格	 2023/6/7




32	GX-B1500/21-1-23071	2023. 6. 7	综合判定：合格		
33	GX-B1500/21-1-23072	2023. 6. 7	综合判定：合格		
34	GX-B1500/21-1-23073	2023. 6. 7	综合判定：合格		

35	GX-B1313/21-1-23062~23065	2023. 6. 7	本次共检电力变压器4台，4台电力变压器所检项目合格。		 <p>2023.5.7</p>	
36	GX-B1313/21-1-23058~23061	2023. 6. 7	本次共检电力变压器4台，4台所检项目合格。		 <p>2023.5.7</p>	
37	GX-B1322/21-1-23147~23153	2023. 6. 7	本次共检验电力电缆7条，7条所检项目合格。		 <p>2023.5.7</p>	

38	GX-B1322/21-1-23154~23159	2023. 6. 7	本次共检验电力电缆6条，6条所检项目合格。	
39	GX-B1328/20-1-23051	2023. 6. 7	本次共检绝缘手套8只，8只所检项目合格。	
40	GX-B1328/20-1-23052	2023. 6. 7	本次共检绝缘鞋8只，8只所检项目合格。	

41	GX-B1328/20-1-23053	2023. 6. 7	本次共检验电器4支，4支所检项目合格。		
42	GX-B1328/20-1-23054	2023. 6. 7	本次共检便携式短路接地线3套，3套所检项目合格。		
43	GX-B1328/20-1-23055	2023. 6. 7	所检项目合格。		


44	GX-B1307/20-1-23057	2023. 6. 7	综合判定：合格。	
45	GX-B1307/20-1-23058	2023. 6. 7	综合判定：合格。	
46	GX-B1312/20-1-23341~23344	2023. 6. 7	本次共检电力变压器 4台，4台电力变压器所检 项目合格	


47	GX-B1321/20-1-23598~23608	2. 23. 6. 7	本次共检电力电缆11条， 11条电力电缆所检项目合格			
48	GX-B1321/20-1-23609~23623	2. 23. 6. 7	本次共检电力电缆15条， 15条电力电缆所检项目合格			
49	GX-B1321/20-1-23624~23636	2. 23. 6. 7	本次共检电力电缆13条， 13条电力电缆所检项目合格			




50	GX-B1417/22-1-23076	2023. 6. 7	综合判定：合格		
51	GX-B1417/22-1-23077	2023. 6. 7	综合判定：合格		
52	GX-B1417/22-1-23078	2023. 6. 7	综合判定：合格		




53	GX-B1417/22-1-23079	2023. 6. 7	综合判定：合格		
54	GX-B1417/22-1-23080	2023. 6. 7	综合判定：合格		
55	GX-B1417/22-1-23081	2023. 6. 7	综合判定：合格		




56	GX-B1417/22-1-23082	2023. 6. 7	综合判定：合格		
57	GX-B1417/22-1-23083	2023. 6. 7	综合判定：合格		
58	GX-B1417/22-1-23084	2023. 6. 7	综合判定：合格		

59	GX-B1417/22-1-23085	2023. 6. 7	综合判定：合格		
60	GX-B1417/22-1-23086	2023. 6. 7	综合判定：合格		
61	GX-B1417/22-1-23087	2023. 6. 7	综合判定：合格		

62	GX-B1417/22-1-23088	2023. 6. 7	综合判定：合格		
63	GX-B1417/22-1-23089	2023. 6. 7	综合判定：合格		
64	GX-B1417/22-1-23090	2023. 6. 7	综合判定：合格		




65	GX-B1417/22-1-23091	2023. 6. 7	综合判定：合格		
66	GX-B1417/22-1-23092	2023. 6. 7	综合判定：合格		
67	GX-B1417/22-1-23093	2023. 6. 7	综合判定：合格		

68	GX-B1417/22-1-23094	2023. 6. 7	综合判定：合格		
69	GX-B1417/22-1-23095	2023. 6. 7	综合判定：合格		
70	GX-B1417/22-1-23096	2023. 6. 7	综合判定：合格		

71	GX-B1417/22-1-23097	2023. 6. 7	综合判定：合格	
72	GX-B1417/22-1-23098	2023. 6. 7	综合判定：合格	
73	GX-B1417/22-1-23099	2023. 6. 7	综合判定：合格	

74	GX-B1350/21-1-23016	2023/6/7	本次共检验接地装置 2处，2处所检项目合格。	 <p>A photograph showing a worker in a red cap and dark clothing kneeling on a concrete surface, inspecting a ground device. The background shows industrial buildings and overhead power lines. A timestamp '2023.06.07' is visible in the bottom right corner of the image.</p>
75	GX-B1423/20-1-23323	2023/6/3	综合判定：合格	 <p>A photograph of a red truck parked on a dirt area. Two workers in light-colored shirts and dark pants are standing in front of the truck. A timestamp '2023.05.20' is visible in the bottom right corner of the image.</p>
76	GX-B1423/20-1-23324	2023/6/3	综合判定：合格	 <p>A photograph of a red truck parked on a dirt area. Two workers in light-colored shirts and dark pants are standing in front of the truck. A timestamp '2023.05.20' is visible in the bottom right corner of the image.</p>

77	GX-B1423/20-1-23325	2023/6/3	综合判定：合格	
78	GX-B1423/20-1-23326	2023/6/3	综合判定：合格	
79	GX-B1423/20-1-23327	2023/6/3	综合判定：合格	

80	GX-B1423/20-1-23328	2023/6/3	综合判定：合格	
81	GX-B1423/20-1-23329	2023/6/3	综合判定：合格	
82	GX-B1423/20-1-23330	2023/6/3	综合判定：合格	

83	GX-B1423/20-1-23331	2023/6/3	综合判定：合格	
84	GX-B1423/20-1-23332	2023/6/3	综合判定：合格	
85	GX-B1423/20-1-23333	2023/6/3	综合判定：合格	



86	GX-B1423/20-1-23334	2023/6/3	综合判定：合格	
87	GX-B1423/20-1-23335	2023/6/3	综合判定：合格	
88	GX-B1423/20-1-23336	2023/6/3	综合判定：合格	

89	GX-B1423/20-1-23337	2023/6/3	综合判定：合格	
90	GX-B1423/20-1-23338	2023/6/3	综合判定：合格	
91	GX-B1423/20-1-23339	2023/6/3	综合判定：合格	

92	GX-B1534/20-1-23019	2023. 6. 7	所检项目合格	 <p>2023.05.08</p>
93	GX-B1534/20-1-23020	2023. 6. 7	所检项目合格	 <p>2023.05.08</p>
94	GX-B1534/20-1-23021	2023. 6. 7	所检项目合格	 <p>2023.05.08</p>

95	GX-B1534/20-1-23022	2023. 6. 7	所检项目合格	
96	GX-B1534/20-1-23023	2023. 6. 7	所检项目合格	
97	GX-B1423/20-1-23273	2023. 6. 9	综合判定：合格	

98	GX-B1423/20-1-23274	2023. 6. 9	综合判定：合格	 A white truck with a red stripe and a circular logo on the front. Two men in safety gear stand in front of it. A red timestamp '2023/5/11' is at the bottom right.
99	GX-B1423/20-1-23275	2023. 6. 9	综合判定：合格	 A white truck with a red stripe and a circular logo on the front. Two men in safety gear stand in front of it. A red timestamp '2023/5/11' is at the bottom right.
100	GX-B1423/20-1-23276	2023. 6. 9	综合判定：合格	 A yellow truck with a large front grille and a circular logo. Three people are standing in front of it. A red timestamp '2023/5/11' is at the bottom right.

101	GX-B1423/20-1-23277	2023. 6. 9	综合判定：合格	
102	GX-B1423/20-1-23278	2023. 6. 9	综合判定：合格	
103	GX-B1423/20-1-23279	2023. 6. 9	综合判定：合格	

104	GX-B1423/20-1-23280	2023. 6. 9	综合判定：合格	
105	GX-B1423/20-1-23281	2023. 6. 9	综合判定：合格	