




序号	报告编号	发布日期	结论	影像资料
140	GX-B1305/21-2-23002	2023. 6. 9	综合判定：合格。	 <p>2023/05/22</p>
141	GX-B1310/21-2-23113	2023. 6. 10	符合标准要求	 <p>2023/05/28</p>
142	GX-B1427/21-2-23113	2023. 6. 10	符合标准要求	 <p>2023/05/28</p>




143	GX-B1310/21-2-23080	2023. 6. 12	符合标准要求。		
144	GX-B1427/21-2-23080	2023. 6. 12	符合标准要求。		
145	GX-B1423/20-2-23066	2023. 6. 13	综合判定：合格		

146	GX-B1423/20-2-23067	2023. 6. 13	综合判定：合格	
147	GX-B1423/20-2-23068	2023. 6. 13	综合判定：合格	
148	GX-B1423/20-2-23069	2023. 6. 13	综合判定：合格	

149	GX-B1423/20-2-23070	2023. 6. 13	综合判定：合格	 A photograph showing two men standing in front of a yellow truck. The man on the left is wearing a white t-shirt and dark pants, while the man on the right is wearing a light blue shirt and dark pants. The truck is a large yellow vehicle with a green tarp on its bed. The date '2023/06/13' is visible in the bottom right corner of the photo.
150	GX-B1423/20-2-23071	2023. 6. 13	综合判定：合格	 A photograph showing a man in a red hard hat and light blue shirt inspecting a yellow truck. He is holding a clipboard and looking at the truck. The truck is a large yellow vehicle with a green tarp on its bed. The date '2023/06/13' is visible in the bottom right corner of the photo.
151	GX-B1423/20-2-23072	2023. 6. 13	综合判定：合格	 A photograph showing two men standing in front of a yellow truck. The man on the left is wearing a light blue shirt and dark pants, while the man on the right is wearing a white t-shirt and shorts. The truck is a large yellow vehicle with a green tarp on its bed. The date '2023/06/13' is visible in the bottom right corner of the photo.




152	GX-B1423/20-2-23073	2023. 6. 13	综合判定：合格	 A photograph showing two men standing in front of a yellow truck. The man on the left is wearing a blue t-shirt and black shorts, while the man on the right is wearing a white shirt and black pants. The truck is a large yellow vehicle with a canopy. A timestamp '2023/06/13' is visible in the bottom right corner of the image.
153	GX-B1423/20-2-23074	2023. 6. 13	综合判定：合格	 A photograph showing a man sitting in the driver's seat of a yellow truck, operating the vehicle. The man is wearing a white shirt and dark pants. The interior of the truck is visible, including the steering wheel and dashboard. A timestamp '2023/06/13' is visible in the bottom right corner of the image.
154	GX-B1499/21-2-23050	2023. 6. 13	所检项目合格	 A photograph showing a worker in an orange safety suit and helmet operating a piece of machinery, possibly a pump or motor, in an industrial setting. The worker is wearing a red helmet and an orange safety suit. The machinery is blue and white. A timestamp '2023/05/09' is visible in the bottom right corner of the image.

155	GX-B1499/21-2-23051	2023. 6. 13	所检项目合格		 2023/05/09	
156	GX-B1499/21-2-23052	2023. 6. 13	所检项目合格		 2023/05/09	
157	GX-1495/20-2-23342~23357	2023. 6. 12	所检项目合格		 2023/05/16	




158	GX-1495/20-2-23358~23369	2023. 6. 12	所检项目合格	 <p>A photograph showing three workers in blue uniforms and red hard hats working in a tunnel. They are gathered around a piece of equipment, possibly a generator or motor, and appear to be inspecting it. The tunnel walls are lined with reflective material, and there are some signs on the wall.</p>
159	GX-1495/20-2-23370~23381	2023. 6. 12	所检项目合格	 <p>A photograph showing two workers in blue uniforms and red hard hats working in a tunnel. They are standing next to a piece of equipment, possibly a generator or motor, and appear to be inspecting it. The tunnel walls are lined with reflective material, and there are some signs on the wall. The date 2023/05/18 is visible in the bottom right corner.</p>
160	GX-B1495/20-2-23412~23419	2023. 6. 13	所检项目合格	 <p>A photograph showing two workers in blue uniforms and red hard hats working in a tunnel. They are standing next to a piece of equipment, possibly a generator or motor, and appear to be inspecting it. The tunnel walls are lined with reflective material, and there are some signs on the wall. The date 2023/05/20 is visible in the bottom right corner.</p>

161	GX-B1495/20-2-23420~23427	2023. 6. 13	所检项目合格	
162	GX-B1495/20-2-23428~23443	2023. 6. 13	所检项目合格	
163	GX-B1495/20-2-23444~23459	2023. 6. 13	所检项目合格	






164	GX-B1350/20-2-23023	2023. 6. 12	所检项目合格	 <p>2023/05/20</p>
165	GX-B1539/22-2-23006	2023. 6. 14	所检项目合格	 <p>2023/05/24</p>
166	GX-B1539/22-2-23007	2023. 6. 14	所检项目合格	 <p>2023/05/24</p>

167	GX-B1539/22-2-23008	2023. 6. 14	所检项目合格	 <p>2023/05/24</p>
168	GX-B1539/22-2-23009	2023. 6. 14	所检项目合格	 <p>2023/05/24</p>
169	GX-B1539/22-2-23010	2023. 6. 14	所检项目合格	 <p>2023/05/25</p>

170	GX-B1539/22-2-23011	2023. 6. 14	所检项目合格	 <p>2023/05/25</p>
171	GX-B1539/22-2-23012	2023. 6. 14	所检项目合格	 <p>2023/05/25</p>
172	GX-B1539/22-2-23013	2023. 6. 14	所检项目合格	 <p>2023/05/25</p>

173	GX-B1539/22-2-23014	2023. 6. 14	所检项目合格	
174	GX-B1495/20-2-23494~23497	2023. 6. 12	本次共检高压防爆开关4台，4台高压防爆开关所检项目合格。	
175	GX-B1321/20-2-23230~23240	2023. 6. 14	本次共检电力电缆11条，11条电力电缆所检项目合格。	

176	GX-B1321/20-2-23206~23218	2023.6.14	本次共检电力电缆13条，13条电力电缆所检项目合格。	
177	GX-B1321/20-2-23219~23229	2023.6.14	本次共检电力电缆11条，11条电力电缆所检项目合格。	
178	GX-B1312/20-2-23140	2023.6.14	本次所检项目合格。	




179	GX-B1312/20-2-23139	2023. 6. 14	本次所检项目合格。	
180	GX-B1321/20-2-23245~23251	2023. 6. 14	所检项目合格	
181	GX-B1321/20-2-23252~23258	2023. 6. 14	所检项目合格	




182	GX-B1312/20-2-23154~23155	2023. 6. 14	所检项目合格	
183	GX-B1312/20-2-23141~23143	2023/6/13	本次共检电力变压器3台，3台电力变压器所检项目合格。	
184	GX-B1321/20-2-23115~23126	2023. 6. 14	所检项目合格	

185	GX-B1321/20-2-23127~23133	2023. 6. 14	所检项目合格	
186	GX-B1321/20-2-23134~23140	2023. 6. 14	所检项目合格	
187	GX-B1305/21-2-23003	2023/6/15	综合判定：合格	




188	GX-B1303/21-2-23003	2023. 6. 15	综合判定：合格。	
189	GX-B1328/20-2-23100	2023. 6. 15	所检项目合格	
190	GX-B1328/20-2-23101	2023. 6. 15	所检项目合格	

191	GX-B1312/20-2-23144~23147	2023. 6. 15	所检项目合格			
192	GX-B1312/20-2-23124~23129	2023. 6. 15	所检项目合格			
193	GX-B1312/20-2-23130~23138	2023. 6. 15	所检项目合格			

194	GX-B1306/21-2-23035	2023.6.14	<p>1、无储气罐检验证书；</p> <p>2. 容积流量小于0.85倍的压缩机铭牌容积流量；</p> <p>3. 比功率大于6.3 kW/ (m<sup>3</sup>/min)。</p> <p>除以上问题外，其余所检项目合格。</p>	
195	GX-B1306/21-2-23036	2023.6.14	<p>1、无储气罐检验证书；</p> <p>2. 容积流量小于0.85倍的压缩机铭牌容积流量；</p> <p>3. 比功率大于6.3 kW/ (m<sup>3</sup>/min)。</p> <p>除以上问题外，其余所检项目合格。</p>	
196	GX-B1306/21-2-23037	2023.6.14	<p>1、无储气罐检验证书；</p> <p>2. 容积流量小于0.85倍的压缩机铭牌容积流量；</p> <p>3. 比功率大于6.3 kW/ (m<sup>3</sup>/min)。</p> <p>除以上问题外，其余所检项目合格。</p>	

197	GX-B1306/21-2-23041	2023. 6. 14	所检项目合格。		
198	GX-B1306/21-2-23042	2023. 6. 14	所检项目合格。		
199	GX-B1306/21-2-23043	2023. 6. 14	所检项目合格。		

200	GX-B1535/21-2-23001	2023. 6. 14	所检项目合格。	
-----	---------------------	-------------	---------	---