

序号	报告编号	发布日期	结论	影像资料
1	GX-B1363/22-A-23291	2023/7/3	所检项目合格。	 A photograph showing two workers in white uniforms inspecting a large, rusted industrial furnace. The furnace has a tall chimney pipe on top and several doors with yellow warning labels. The date stamp '2023/06/29' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
2	GX-B1363/22-A-23293	2023/7/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3	GX-B1363/22-A-23292	2023/7/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
4	GX-B1363/22-A-23290	2023/7/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
5	GX-B1363/22-A-23289	2023/7/4	覆盖胶拉伸强度、全厚度拉伸强度及阻燃性能不合格，全厚度拉断伸长率结果见报告内页；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
6	GX-B1363/22-A-23288	2023/7/4	所检项目合格。	 <p>The photograph shows two men in light blue work shirts and dark trousers inspecting a large, weathered metal electrical cabinet. One man on the left is wearing blue gloves and is touching the cabinet door. The man on the right is looking into an open compartment of the cabinet. The cabinet has several yellow warning triangles with black exclamation marks. In the background, there is a window with a view of greenery outside. A date stamp '2023/06/28' is visible in the bottom right corner of the photo.</p>

序号	报告编号	发布日期	结论	影像资料
7	GX-B1363/22-A-23287	2023/7/4	所检项目合格。	