

序号	报告编号	发布日期	结论	影像资料
1	GX-B1328/20-1-23056	2023. 8. 1	本次共检绝缘手套6只，6只所检项目合格	
2	GX-B1328/20-1-23057	2023. 8. 1	本次共检绝缘鞋6只，6只所检项目合格	
3	GX-B1328/20-1-23058	2023. 8. 1	本次共检绝缘杆3组，3组所检项目合格	

4	GX-B1385/21-1-23018	2023. 8. 2	所检项目合格	
5	GX-B1517/20-1-23031	2023. 8. 3	综合判定：合格	
6	GX-B1517/20-1-23032	2023. 8. 3	综合判定：合格	

7	GX-B1517/20-1-23033	2023. 8. 3	综合判定：合格	
8	GX-B1517/20-1-23034	2023. 8. 3	综合判定：合格	
9	GX-B1517/20-1-23035	2023. 8. 3	综合判定：合格	

10	GX-B1306/21-1-23036	2023/8/3	所检项目合格	 A worker in a white t-shirt and red hard hat stands next to a large, grey metal electrical cabinet in a room with a green floor. A date stamp '2023.07.07' is visible in the bottom right corner of the photo.
11	GX-B1306/21-1-23037	2023/8/3	所检项目合格	 A worker in a white t-shirt and red hard hat is touching a grey metal electrical cabinet. The worker is standing on a green floor. A date stamp '2023.07.07' is visible in the bottom right corner of the photo.
12	GX-B1306/21-1-23038	2023/8/3	所检项目合格	 A worker in a white t-shirt and red hard hat is kneeling on a green floor next to a yellow electrical cabinet. The worker is holding a tool. A date stamp '2023.07.07' is visible in the bottom right corner of the photo.

13	GX-B1428/21-1-23101	2023/8/4	无缺陷痕迹显示	
14	GX-B1534/20-1-23024	2023/8/4	所检项目合格	

23045









