

序号	报告编号	发布日期	结论	影像资料
1	GX-B1495/20-3-235484 ~ 235492	2023年9月1日	本次共检高压开关设备9台， 9台高压开关设备所检项目合格	
2	GX-B1352/21-3-23397	2023年9月1日	所检项目合格	
3	GX-B1328/20-3-23191	2023年9月1日	本次共检绝缘手套50只，50 只绝缘手套合格	

4	GX-B1328/20-3-23192	2023年9月1日	本次共检绝缘鞋50只，50只绝缘鞋合格	 <p>2023.8.31</p>
5	GX-B1522/20-3-23003	2023年9月2日	所检项目合格	 <p>2023.08.25</p>
6	GX-B1522/20-3-23004	2023年9月2日	所检项目合格	 <p>2023.08.25</p>

7	GX-B1522/20-3-23005	2023年9月2日	所检项目合格	
8	GX-B1522/20-3-23006	2023年9月2日	所检项目合格	
9	GX-B1321/20-3-231700~231713	2023年9月4日	本次共检电力电缆14条，14条电力电缆所检项目合格。	

10	GX-B1423/20-3-23101	2023年9月2日	综合判定：合格	 A photograph showing a person wearing a red hard hat and a light blue short-sleeved shirt operating a piece of heavy machinery from the driver's seat inside the cab. The date stamp '2023.09.25' is visible in the bottom right corner of the image.
11	GX-B1423/20-3-23102	2023年9月2日	综合判定：合格	 A photograph of a person wearing a red hard hat, glasses, and a light blue short-sleeved shirt standing next to a large piece of white machinery. The person is looking towards the camera. The date stamp '2023.09.25' is visible in the bottom right corner of the image.
12	GX-B1423/20-3-23103	2023年9月2日	综合判定：合格	 A photograph showing a person wearing a red hard hat and a light blue short-sleeved shirt operating a piece of heavy machinery from the driver's seat inside the cab. The date stamp '2023.09.25' is visible in the bottom right corner of the image.

13	GX-B1423/20-3-23104	2023年9月2日	综合判定：合格	 <p>2023.08.25</p>
14	GX-B1423/20-3-23105	2023年9月2日	综合判定：合格	 <p>2023.08.25</p>
15	GX-B1423/20-3-23106	2023年9月2日	综合判定：合格	 <p>2023.08.25</p>

16	GX-B1423/20-3-23107	2023年9月2日	综合判定：合格	
17	GX-B1423/20-3-23108	2023年9月2日	综合判定：合格	
18	GX-B1423/20-3-23109	2023年9月2日	综合判定：合格	

19	GX-B1423/20-3-23110	2023年9月2日	综合判定：合格		
20	GX-B1423/20-3-23111	2023年9月2日	综合判定：合格		
21	GX-B1423/20-3-23112	2023年9月2日	综合判定：合格		

22	GX-B1423/20-3-23113	2023年9月2日	综合判定：合格	
23	GX-B1423/20-3-23114	2023年9月2日	综合判定：合格	
24	GX-B1423/20-3-23115	2023年9月2日	综合判定：合格	



25	GX-B1423/20-3-23116	2023年9月2日	综合判定：合格	
26	GX-B1423/20-3-23117	2023年9月2日	综合判定：合格	
27	GX-B1423/20-3-23118	2023年9月2日	综合判定：合格	

28	GX-B1423/20-3-23119	2023年9月2日	综合判定：合格	 A photograph showing a person wearing a red hard hat and safety glasses sitting in the operator's seat of a yellow excavator. The person is looking towards the camera. The date '2023.08.26' is visible in the bottom right corner of the image.
29	GX-B1423/20-3-23120	2023年9月2日	综合判定：合格	 A photograph showing a person wearing a red hard hat and safety glasses sitting in the operator's seat of a yellow excavator. The person is looking towards the camera. The date '2023.08.26' is visible in the bottom right corner of the image.
30	GX-B1423/20-3-23121	2023年9月2日	综合判定：合格	 A photograph showing a person wearing a red hard hat and safety glasses sitting in the operator's seat of a yellow excavator. The person is looking towards the camera. The date '2023.08.26' is visible in the bottom right corner of the image.

31	GX-B1423/20-3-23122	2023年9月2日	综合判定：合格	
32	GX-B1548/20-3-23014	2023年9月4日	所检项目合格	
33	GX-B1415/22-3-23029	2023年9月4日	所检项目合格	

34	GX-B1415/22-3-23030	2023年9月4日	所检项目合格		
35	GX-B1416/22-3-23038	2023年9月4日	综合判定：合格		
36	GX-B1310/21-3-23175	2023年9月4日	未发现超过 \varnothing 2mm当量直径的缺陷		

37	GX-B1310/21-3-23176	2023年9月4日	未发现超过 \varnothing 2mm当量直径的缺陷	
38	GX-B1310/21-3-23173	2023年9月4日	未发现超过 \varnothing 2mm当量直径的缺陷	
39	GX-B1310/21-3-23174	2023年9月4日	未发现超过 \varnothing 2mm当量直径的缺陷	

40	GX-B1428/21-3-23031	2023年9月4日	无缺陷痕迹显示	 A worker in a blue uniform and red helmet is inspecting a large blue cylindrical component. A yellow timestamp '2023.08.23' is visible in the bottom right corner of the image.
41	GX-B1428/21-3-23032	2023年9月4日	无缺陷痕迹显示	 A worker in a blue uniform and red helmet is inspecting a large blue cylindrical component. A yellow timestamp '2023.08.25' is visible in the bottom right corner of the image.
42	GX-B1328/20-3-23206	2023. 9. 4	本次共检绝缘手套4只，4只绝缘手套合格。	
43	GX-B1328/20-3-23207	2023. 9. 4	本次共检绝缘鞋4只，4只绝缘鞋合格。	

44	GX-B1310/21-3-23167	2023年9月5日	符合标准要求		
45	GX-B1310/21-3-23168	2023年9月5日	符合标准要求		
46	GX-B1310/21-3-23169	2023年9月5日	符合标准要求		

47	GX-B1427/21-3-23040	2023年9月5日	符合标准要求		
48	GX-B1427/21-3-23041	2023年9月5日	符合标准要求		
49	GX-B1427/21-3-23042	2023年9月5日	符合标准要求		

50	GX-B1415/22-3-23031	2023.9.5	综合判定：合格。	
51	GX-B1321/20-3-231699	2023.9.6	所检项目合格	

52	GX-B1312/20-3-23635~23636	2023. 9. 6	本次共检测电力变压器 2台，2台电力变压器所检 项目合格	
53	GX-B1310/21-3-23177	2023年9月6日	未发现超过 \varnothing 2mm当量直径的 缺陷	
54	GX-B1310/21-3-23178	2023年9月6日	未发现超过 \varnothing 2mm当量直径的 缺陷	

55	GX-B1310/21-3-23179	2023年9月6日	未发现超过 \varnothing 2mm当量直径的缺陷	
56	GX-B1520/20-3-23039	2023. 9. 5	综合判定：合格。	
57	GX-B1520/20-3-23040	2023. 9. 5	综合判定：合格。	

58	GX-B1548/20-3-23024	2023.9.5	所检项目合格。	 A photograph showing a man in a black shirt standing next to the rear of a yellow vehicle. The vehicle has a red and white reflective strip on the back. A date stamp '2023/8/11' is visible in the bottom right corner of the photo.
59	GX-B1548/20-3-23023	2023.9.5	所检项目合格。	 A photograph showing a man in a dark blue long-sleeved shirt with 'L'VEL VE' on the front standing next to an orange vehicle. The vehicle has a white roof and red and white reflective strips. The word 'FELLO' is visible on the side of the vehicle. A date stamp '2023/9/5' is visible in the bottom right corner of the photo.