













序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-6-23122	2023/9/1	符合标准要求	
2	GX-B1310/21-6-23118	2023/9/1	符合标准要求	
3	GX-B1423/20-6-23929	2023/9/4	综合判定合格	

4	GX-B1423/20-6-23930	2023/9/4	综合判定合格		
5	GX-B1423/20-6-23931	2023/9/4	综合判定合格		
6	GX-B1423/20-6-23932	2023/9/4	综合判定合格		
7	GX-B1423/20-6-23933	2023/9/4	综合判定合格		



8	GX-B1423/20-6-23937	2023/9/4	综合判定合格		
9	GX-B1423/20-6-23938	2023/9/4	综合判定合格		
10	GX-B1423/20-6-23939	2023/9/4	综合判定合格		
11	GX-B1423/20-6-23940	2023/9/4	综合判定合格		





12	GX-B1423/20-6-23941	2023/9/4	综合判定合格			
13	GX-B1423/20-6-23942	2023/9/4	综合判定合格			
14	GX-B1423/20-6-23934	2023/9/4	综合判定合格			
15	GX-B1423/20-6-23935	2023/9/4	综合判定合格			

16	GX-B1423/20-6-23936	2023/9/4	综合判定合格			
17	GX-B1423/20-6-23943	2023/9/4	综合判定合格			
18	GX-B1500/21-6-23125	2023/9/4	见报告第三页： 单台水泵启动时间不大于5分钟，合格；流量为95.2			
19	GX-B1500/21-6-23126	2023/9/4	见报告第三页： 单台水泵启动时间不大于5分钟，合格；流量为96.1			

20	GX-B1423/20-6-23921	2023/9/4	综合判定合格		
21	GX-B1423/20-6-23922	2023/9/4	综合判定合格		
22	GX-B1423/20-6-23923	2023/9/4	综合判定合格		
23	GX-B1423/20-6-23924	2023/9/4	综合判定合格		

24	GX-B1423/20-6-23925	2023/9/4	综合判定合格	
25	GX-B1423/20-6-23926	2023/9/4	综合判定合格	
26	GX-B1423/20-6-23927	2023/9/4	综合判定合格	
27	GX-B1423/20-6-23928	2023/9/4	综合判定合格	

28	GX-B1321/20-6-23777~23778	2023/9/5	所检项目合格			
29	GX-B1328/20-6-23116	2023/9/5	所检项目合格			
30	GX-B1328/20-6-23117	2023/9/5	所检项目合格			
31	GX-B1328/20-6-23118	2023/9/5	所检项目合格			

32	GX-B1328/20-6-23119	2023/9/5	所检项目合格			
33	GX-B1328/20-6-23120	2023/9/5	所检项目合格			
34	GX-B1312/20-6-23355~23360	2023/9/5	所检项目合格			
35	GX-B1451/20-6-23645	2023/8/31	所检项目合格			

36	GX-B1321/20-6-23779~23783	2023/9/6	所检项目合格			
----	---------------------------	----------	--------	--	---	--

