







| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------|-----------|--------|--|
| 30 | GX-B1310/21-5-23240 | 2023/9/19 | 符合标准要求 |  |
| 31 | GX-B1310/21-5-23241 | 2023/9/19 | 符合标准要求 |  |


| | | | | |
|----|---------------------|-----------|-----------------------------|--|
| 32 | GX-B1310/21-5-23242 | 2023/9/19 | 符合标准要求 |  |
| 33 | GX-B1424/20-5-23042 | 2023/9/19 | 依据NB/T 10176-2019 综合判定合格 |  |
| 34 | GX-B1424/20-5-23043 | 2023/9/19 | 依据NB/T 10176-2019 综合判定合格 |  |

| | | | | |
|----|---------------------|-----------|----------|--|
| 35 | GX-B1306/21-5-23075 | 2023/9/19 | 所检项目合格 |  A worker wearing a red hard hat and a light-colored short-sleeved shirt is inspecting a piece of machinery. The worker is standing on a light-colored floor, and the machinery is dark-colored. A yellow timestamp '2023/9/17' is visible in the bottom right corner of the photo. |
| 36 | GX-B1415/22-5-23018 | 2023/9/20 | 综合判定：合格。 |  A worker wearing a hard hat and a safety vest is inspecting machinery in a confined space. The worker is kneeling or sitting on the floor, and the machinery is complex and metallic. A yellow timestamp '2023/9/12' is visible in the bottom right corner of the photo. |
| 37 | GX-B1517/20-5-23027 | 2023/9/20 | 综合判定：合格。 |  A worker wearing a blue uniform and a hard hat is inspecting the interior of a white vehicle. The worker is sitting on the floor, and the interior of the vehicle is visible. A yellow timestamp '2023/9/12' is visible in the bottom right corner of the photo. |

| | | | | |
|----|---------------------------|-------------|--------------------------|---|
| 38 | GX-B1310/21-5-23243 | 2023/9/22 | 符合标准要求。 |  |
| 39 | GX-B1321/20-5-23890~23897 | 2023. 9. 25 | 本次共检电力电缆8条，8条电力电缆所检项目合格。 |  |
| 40 | GX-B1328/20-5-23152 | 2023. 9. 25 | 本次共检绝缘手套140只，140只绝缘手套合格。 |  |

| | | | | |
|----|---------------------|-------------|--------------------------------------|--|
| 41 | GX-B1328/20-5-23153 | 2023. 9. 25 | 本次共检绝缘鞋 92只，92只绝缘鞋合 格。 |  |
| 42 | GX-B1424/20-5-23044 | 2023/9/27 | 依据NB/T 10176-2019 单轨吊车所检项目合 格。 |  |
| 43 | GX-B1424/20-5-23045 | 2023/9/27 | 依据NB/T 10176-2019 单轨吊车综合判定合 格。 |  |

| | | | | | | |
|----|---------------------|-----------|---------|--|---|--|
| 44 | GX-B1310/21-5-23244 | 2023/9/27 | 符合标准要求。 | |  <p>2023/9/12</p> | |
| 45 | GX-B1311/21-5-23228 | 2023/9/27 | / | |  <p>2023/8/18</p> | |
| 46 | GX-B1311/21-5-23229 | 2023/9/27 | / | |  <p>2023/8/18</p> | |

| | | | | | | |
|----|---------------------|-----------|---|--|--|--|
| 47 | GX-B1311/21-5-23230 | 2023/9/27 | / | |  A photograph showing two workers in a confined space. Both are wearing red hard hats and high-visibility safety vests. The worker on the left is wearing a blue shirt, and the worker on the right is wearing a dark grey shirt. They appear to be focused on a task. A date stamp '2023/8/18' is visible in the bottom right corner of the photo. | |
|----|---------------------|-----------|---|--|--|--|