

序号	报告编号	发布日期	结论	影像资料
3	GX-B1302/23-7-23002	2023. 11. 8	综合判定：合格。	 <p>A photograph showing two workers in a factory environment. One worker is wearing a red hard hat and a brown jacket, standing near a large green industrial machine. The other worker is wearing a grey jacket and blue jeans, holding a clipboard. The machine has a digital display showing '1111'. A date stamp '2023.10.28' is visible in the bottom right corner of the image.</p>
4	GX-B1517/20-7-23074	2023/11/9	综合判定：合格。	 <p>A photograph taken in a dimly lit tunnel or underground facility. Two workers wearing red hard hats and reflective safety gear are standing next to a red piece of equipment. One worker is holding a clipboard. The scene is illuminated by overhead lights. A date stamp '2023/11/3' is visible in the bottom right corner of the image.</p>
5	GX-B1517/20-7-23075	2023/11/9	综合判定：合格。	 <p>A photograph similar to the previous one, showing two workers in a tunnel or underground facility. They are wearing red hard hats and reflective safety gear, standing next to a red piece of equipment. One worker is holding a clipboard. The scene is illuminated by overhead lights. A date stamp '2023/11/3' is visible in the bottom right corner of the image.</p>