



序号	报告编号	发布日期	结论	影像资料
60	GX-B1382/21-3-24002	2024. 2. 8	所检项目合格。	
61	GX-B1382/21-3-24003	2024. 2. 8	所检项目合格。	

62	GX-B1382/21-3-24004	2024. 2. 8	所检项目合格。			
63	GX-B1382/21-3-24005	2024. 2. 8	所检项目合格。			

64	GX-B1382/21-3-24006	2024. 2. 8	所检项目合格。			
65	GX-B1382/21-3-24007	2024. 2. 8	所检项目合格。			

66	GX-B1359/21-3-24021~24028	2024. 2. 8	本次共检矿用隔爆型照明信号综合保护装置8台, 8台所检项目合格。			
67	GX-B1359/21-3-24029~24047	2024. 2. 8	本次共检矿用隔爆型照明信号综合保护装置19台, 19台所检项目合格。			

68	GX-B1324/21-3-24001	2024. 2. 20	本次共检三相交流电动机1台，1台三相交流电动机所检项目合格。	 <p>XIAOMI 14 23mm f/1.6 1/76s ISO100</p>
69	GX-B1520/20-3-24002	2024年2月20日	综合判定：合格。	 <p>2024.2.19</p>

70	GX-B1517/20-3-24001	2024. 2. 19	综合判定： 合格			
71	GX-B1517/20-3-24002	2024. 2. 19	综合判定： 合格			




72	GX-B1517/20-3-24003	2024. 2. 19	综合判定： 合格			
73	GX-B1517/20-3-24004	2024. 2. 19	综合判定： 合格			

74	GX-B1517/20-3-24005	2024. 2. 19	综合判定： 合格			
75	GX-B1517/20-3-24006	2024. 2. 19	综合判定： 合格			



76	GX-B1559/22-3-24001	2024年2月21日	所检项目合格。	
77	GX-B1559/22-3-24002	2024年2月21日	所检项目合格。	

78	GX-B1559/22-3-24003	2024年2月21日	所检项目合格。	
79	GX-B1559/22-3-24004	2024年2月21日	所检项目合格。	


80	GX-B1559/22-3-24005	2024年2月21日	所检项目合格。	 A photograph of a male worker wearing a light-colored, possibly grey or white, jacket and a red hard hat. He is standing in an industrial setting, next to what appears to be a piece of heavy machinery. The date '2023.12.26' is visible in the bottom right corner of the photo.
81	GX-B1559/22-3-24006	2024年2月21日	所检项目合格。	 A photograph of a male worker wearing a dark jacket and a red hard hat. He is standing outdoors in an industrial area, in front of a yellow forklift. The date '2023.12.26' is visible in the bottom right corner of the photo.



82	GX-B1559/22-3-24007	2024年2月21日	所检项目合格。	 <p>2023.12.26</p>
83	GX-B1559/22-3-24008	2024年2月21日	所检项目合格。	 <p>2023.12.26</p>

84	GX-B1559/22-3-24009	2024年2月21日	所检项目合格。	 A photograph showing a worker in a red hard hat and dark jacket standing in a large industrial warehouse. In the background, a red truck is parked. The date '2023.12.26' is visible in the bottom right corner of the photo.
85	GX-B1559/22-3-24010	2024年2月21日	所检项目合格。	 A photograph of a worker wearing a red hard hat and a dark jacket, standing in front of a yellow forklift. The worker is smiling at the camera. The date '2023.12.26' is visible in the bottom right corner of the photo.

86	GX-B1559/22-3-24011	2024年2月21日	所检项目合格。	 <p>2023.12.26</p>
87	GX-B1559/22-3-24012	2024年2月21日	所检项目合格。	 <p>2023.12.26</p>



88	GX-B1559/22-3-24013	2024年2月21日	所检项目合格。	
89	GX-B1515/22-3-24001	2024. 2. 21	所检项目合格。	

90	GX-B1515/22-3-24002	2024. 2. 21	所检项目合格。		 <p>2024.1.10</p>	
91	GX-B1415/22-3-24001	2024年2月21日	综合判定：合格		 <p>2024.01:08</p>	


92	GX-B1415/22-3-24002	2024年2月21日	综合判定： 合格			
93	GX-B1415/22-3-24003	2024年2月21日	综合判定： 合格			

94	GX-B1415/22-3-24004	2024年2月21日	综合判定：合格	
95	GX-B1308/23-3-24001	2024年2月22日	所检项目合格。	

96	GX-B1499/23-3-24001	2024年2月22日	所检项目合格。	
97	GX-B1499/23-3-24002	2024年2月22日	所检项目合格。	

98	GX-B1499/23-3-24003	2024年2月22日	所检项目合格。	 A photograph showing a worker in a blue uniform and red helmet working on a piece of equipment. The worker is wearing white gloves and is focused on the task. The background is dark, and there is a timestamp '2024.2.7' in the bottom right corner of the image.
99	GX-B1499/23-3-24004	2024年2月22日	所检项目合格。	 A photograph showing a worker in a blue uniform and red helmet standing next to a piece of equipment. The worker is wearing a safety harness and is looking towards the camera. The equipment is blue and yellow, and there is a warning sign with a lightning bolt symbol and Chinese text. The background is a brightly lit industrial setting. There is a timestamp '2024.2.7' in the bottom right corner of the image.



100	GX-B1499/23-3-24005	2024年2月22日	所检项目合格。	 <p>2024.2.7</p>
-----	---------------------	------------	---------	---