

序号	报告编号	发布日期	结论	影像资料
1	GX-B1563/21-2-24002	2024. 4. 2	所检项目合格	
2	GX-B1451/20-2-24169~24174	2024. 4. 1	所检项目合格	

3	GX-B1563/21-2-24001	2024. 4. 2	所检项目合格	 <p>2024/03/08</p>
4	GX-B1500/21-2-24030	2024. 4. 1	所检项目合格	 <p>2024/03/20</p>

5	GX-B1500/21-2-24031	2024. 4. 1	所检项目合格	
6	GX-B1500/21-2-24032	2024. 4. 1	所检项目合格	

7	GX-B1382/21-2-24001	2024. 4. 3	合格。	
8	GX-B1382/21-2-24002	2024. 4. 3	合格。	

9	GX-B1380/20-2-24002	2024. 4. 3	所检项目合格。	
10	GX-B1380/20-2-24003	2024. 4. 3	所检项目合格。	

11	GX-B1380/20-2-24004	2024. 4. 3	所检项目合格。			
12	GX-B1415/22-2-24005	2024. 4. 3	综合判定：合格。			

13	GX-B1309/21-2-24006	2024. 4. 3	所检项目合格。	
14	GX-B1309/21-2-24007	2024. 4. 3	所检项目合格。	


15	GX-B1500/21-2-24017	2024. 4. 3	综合判定：合格。	
16	GX-B1500/21-2-24018	2024. 4. 3	综合判定：合格。	



17	GX-B1500/21-2-24019	2024. 4. 3	综合判定：合格。	
18	GX-B1500/21-2-24020	2024. 4. 3	综合判定：合格。	

19	GX-B1500/21-2-24021	2024. 4. 3	综合判定：合格。	 A photograph of industrial machinery in a factory setting. A worker in a blue uniform and red hard hat is standing next to a large green machine. The floor is green. A timestamp '2024/03/20' is visible in the bottom right corner of the image.
20	GX-B1500/21-2-24022	2024. 4. 3	综合判定：合格。	 A photograph of industrial machinery in a factory setting. A worker in a blue uniform and red hard hat is standing next to a large blue machine. The floor is green. A timestamp '2024/03/20' is visible in the bottom right corner of the image.

21	GX-B1500/21-2-24023	2024. 4. 3	综合判定：合格。	
22	GX-B1500/21-2-24024	2024. 4. 3	综合判定：合格。	

23	GX-B1500/21-2-24025	2024. 4. 3	综合判定：合格。	
24	GX-B1500/21-2-24026	2024. 4. 3	综合判定：合格。	



25	GX-B1500/21-2-24027	2024. 4. 3	综合判定：合格。	
26	GX-B1500/21-2-24028	2024. 4. 3	综合判定：合格。	



27	GX-B1500/21-2-24029	2024. 4. 3	综合判定：合格。	
28	GX-B1500/21-2-24030	2024. 4. 3	所检项目合格。	

29	GX-B1500/21-2-24031	2024. 4. 3	综合判定：合格。	
30	GX-B1500/21-2-24032	2024. 4. 3	综合判定：合格。	

31	GX-B1307/20-2-24037	2024. 4. 6	综合判定：合格。	 <p>2024/3/20</p>
32	GX-B1598/21-2-24062	2024. 4. 5	实测钢丝绳有效截面积损失百分比最大为4.70%，小于5%为正常。	 <p>2024/03/27</p>





33	GX-B1598/21-2-24063	2024. 4. 5	实测钢丝绳有效截面积损失百分比最大为4.77%，小于5%为正常。	
34	GX-B1598/21-2-24064	2024. 4. 5	实测钢丝绳有效截面积损失百分比最大为1.08%，小于5%为正常。	


35	GX-B1598/21-2-24065	2024. 4. 5	实测钢丝绳有效截面积损失百分比最大为2.52%，小于5%为正常。	 A photograph showing a worker in a grey uniform and red helmet holding a laptop. The worker is standing on a construction site with metal structures and scaffolding. A date stamp '2024/03/27' is visible in the bottom right corner of the image.
36	GX-B1598/21-2-24066	2024. 4. 5	实测钢丝绳有效截面积损失百分比最大为2.31%，小于5%为正常。	 A photograph showing a worker in a grey uniform and red helmet holding a laptop. The worker is standing on a construction site with metal structures and scaffolding. A date stamp '2024/03/27' is visible in the bottom right corner of the image.

37	GX-B1598/21-2-24067	2024. 4. 5	实测钢丝绳有效截面积损失百分比最大为2.28%，小于5%为正常。	 <p>2024/03/27</p>
38	GX-B1451/20-2-24144~24151	2024. 4. 6	本次共检高压开关柜8台，8台所检项目合格。	 <p>2024/3/16</p>

39	GX-B1451/20-2-24152~24155	2024. 4. 6	本次共检高压开关柜4台，4台所检项目合格。	
40	GX-B1451/20-2-24156~24168	2024. 4. 6	本次共检高压开关柜13台，13台所检项目合格。	

41	GX-B1307/20-2-24038	2024. 4. 6	综合判定：合格。	
42	GX-B1303/21-2-24003	2024. 4. 6	综合判定：合格。	



43	GX-B1307/20-2-24015	2024. 4. 7	综合判定：合格。	
44	GX-B1307/20-2-24016	2024. 4. 7	综合判定：合格。	

45	GX-B1307/20-2-24017	2024. 4. 7	综合判定：合格。	
46	GX-B1307/20-2-24018	2024. 4. 7	综合判定：合格。	

47	GX-B1307/20-2-24019	2024. 4. 7	综合判定：合格。	 <p>2024/03/21</p>
48	GX-B1307/20-2-24020	2024. 4. 7	综合判定：合格。	 <p>2024.03.21</p>



49	GX-B1307/20-2-24021	2024. 4. 7	综合判定：合格。	 A photograph showing two workers in a room with green panels. One worker is standing on the left, and the other is on the right, looking at something. The date '2024/04/07' is visible in the bottom right corner of the photo.
50	GX-B1307/20-2-24022	2024. 4. 7	综合判定：合格。	 A photograph showing two workers in a room with green panels. One worker is on the left, and the other is on the right, looking at something. The date '2024/04/07' is visible in the bottom right corner of the photo.

51	GX-B1307/20-2-24023	2024. 4. 7	综合判定：合格。	 <p>2024/03/21</p>
52	GX-B1307/20-2-24024	2024. 4. 7	综合判定：合格。	 <p>2024/03/21</p>

53	GX-B1307/20-2-24025	2024. 4. 7	综合判定：合格。	
54	GX-B1307/20-2-24026	2024. 4. 7	综合判定：合格。	

55	GX-B1307/20-2-24027	2024. 4. 7	综合判定：合格。	
56	GX-B1307/20-2-24028	2024. 4. 7	综合判定：合格。	

57	GX-B1307/20-2-24029	2024. 4. 7	综合判定：合格。	
58	GX-B1598/21-2-24050	2024. 4. 7	实测钢丝绳有效截面积损失百分比最大为1.57%，小于5%为正常。	

59	GX-B1598/21-2-24051	2024. 4. 7	实测钢丝绳有效截面积损失百分比最大为1.47%，小于5%为正常。	
60	GX-B1598/21-2-24052	2024. 4. 7	实测钢丝绳有效截面积损失百分比最大为1.62%，小于5%为正常。	

61	GX-B1598/21-2-24053	2024. 4. 7	实测钢丝绳有效截面积损失百分比最大为1.69%，小于5%为正常。	
62	GX-B1598/21-2-24054	2024. 4. 7	实测钢丝绳有效截面积损失百分比最大为0.84%，小于5%为正常。	

63	GX-B1598/21-2-24055	2024. 4. 7	实测钢丝绳有效截面积损失百分比最大为1.08%，小于5%为正常。	
64	GX-B1598/21-2-24056	2024. 4. 7	实测钢丝绳有效截面积损失百分比最大为0.80%，小于5%为正常。	




65	GX-B1598/21-2-24057	2024. 4. 7	实测钢丝绳有效截面积损失百分比最大为0.76%，小于5%为正常。	
66	GX-B1598/21-2-24058	2024. 4. 7	实测钢丝绳有效截面积损失百分比最大为0.90%，小于5%为正常。	

67	GX-B1598/21-2-24059	2024. 4. 7	实测钢丝绳有效截面积损失百分比最大为0.81%，小于5%为正常。	
68	GX-B1598/21-2-24060	2024. 4. 7	实测钢丝绳有效截面积损失百分比最大为0.77%，小于5%为正常。	

69	GX-B1598/21-2-24061	2024. 4. 7	实测钢丝绳有效截面积损失百分比最大为0.68%，小于5%为正常。	
70	GX-B1310/21-2-24025	2024. 4. 7	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	

71	GX-B1310/21-2-24029	2024. 4. 7	符合标准要求。	
72	GX-B1310/21-2-24030	2024. 4. 7	符合标准要求。	

73	GX-B1310/21-2-24031	2024. 4. 7	符合标准要求。	 A photograph showing a worker in a red safety suit and helmet operating a large industrial machine, possibly a lathe or mill. The machine is green and blue. The date '2024/3/19' is visible in the bottom right corner of the photo.
74	GX-B1310/21-2-24033	2024. 4. 7	符合标准要求。	 A photograph showing a worker in a grey safety suit and helmet operating a large industrial machine, possibly a lathe or mill. The machine is green and blue. The date '2024/4/7' is visible in the bottom right corner of the photo.

75	GX-B1310/21-2-24034	2024. 4. 7	符合标准要求。	 A photograph showing a worker in a red hard hat and orange safety vest operating a large blue industrial machine. The worker is positioned on the left side of the machine, which has a large circular opening. The background shows an industrial setting with metal railings and other equipment. A small timestamp '2024/03/13' is visible in the bottom right corner of the image.
----	---------------------	------------	---------	--